


## Bildgebung von Beton: Wie der technologieübergreifende Ansatz eine Inspektion von Weltklasse ermöglicht



Proceq GP8000 results showing rebar and a large void (top right). The concrete was cored and the void was confirmed. It is an example of a consolidation void.



SCREENING  
EAGLE



[Terms Of Use](#)  
[Website Data Privacy Policy](#)

**Copyright © 2024 Screening Eagle Technologies. All rights reserved.** The trademarks and logos displayed herein are registered and unregistered trademarks of Screening Eagle Technologies S.A. and/or its affiliates, in Switzerland and certain other countries.